



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program May 5, 2010

Reviewed: 

Mine Name: Lisbon Valley Mine	Permit Number: M/037/0088
Operator Name: Lisbon Valley Mining Company	Inspection Date: April 15, 2010
Inspector(s): T Munson	Time: 10:00 AM
Other Participants: none	Mine Status: active

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)
8. Soils
9. Revegetation

Evaluated

Comment

Enforcement

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$6,076,888

Fees: current

Purpose of Inspection: To discuss exploration projects and new Sentinel backfilling amendment.

Inspection Summary:


The progress on the backfilling project was coming along nicely for the mine and the benefits of this project have been realized. The expansion of the backfill and the implementation of the improved drainage controls in final reclamation will provide adequate surface water protection.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The Division will need to inspect the site on a regular basis and work towards improving the permitting document, as it needs to be updated.

Inspector's Signature

 5/6/2010

TM:vs

cc: Lndergard@lisbonvalley.com

BLM marie_mcgann@blm.gov

O:\M037-SanJuan\M0370088-LisbonValley-Summo\inspections\insp-04152010.doc



	
Sentinel East backfill	Sentinel West
	
Main heap	Heap not being used